








GALANT




Design and Quality
IKEA of Sweden






118331

16x



123492

2x




124327

2x



101350

14x




101375

2x




122971
118137
119081
119253

16x



1x


120076
117434
118224
119030




105867

1x


1





2




3




4






5





6




7






8




9




10




11





12




13



120076
117434
118224
119030




4x




120076
117434
118224
119030


14




15




16




17






18







↓
19





20





21




22




23





24



25

