










GALANT




Design and Quality
IKEA of Sweden







1x



1x




2x




2x



4x






118331

12x




119253
118137

8x




119030
117434

1x




121762

4x



123276

2x




101350

8x




101345

2x




109503

8x




146680

4x




130887

4x




130885

4x




122167

4x





122166

2x




150578


2x




1




2




3




4




5




6




7




8




9




10




11





12




13




14






346679





346683




346682










17







18




19









20





21




22




23





25



26

