








GALANT



Design and Quality
IKEA of Sweden






118331

16x



123492

2x



124327

2x



101350

14x




101375

2x




122971
118137
119081
119253

16x



1x


120076
117434
118224
119030




105867

1x


1




2




3




4





5





6




7






8




9




10




11





12




13



120076
117434
118224
119030




122971 120076
118137 117434
119081 118224
119253 119030




4x
120076
117434
118224
119030


14




15




16




17




18







↓
19





20




21



22





23




2x

122971
118137
119081
119253





24



25

