








# GALANT



Design and Quality  
IKEA of Sweden






118331

10x




122971  
118137  
119081  
119253

10x



120076  
117434  
118224  
119030

1x



124327

2x




101350

8x



101375


4x




105867

1x


**1**





**2**



**3**




120076  
117434  
118224  
119030




122971    120076  
118137    117434  
119081    118224  
119253    119030


1x



120076  
117434  
118224  
119030



**4**





1x



101350

1x


101350

**5**


	
122971	120076
118137	117434
119081	118224
119253	119030






**6**



# 7




2x






# 8




120076  
117434  
118224  
119030



1x




9







# 10





# 11







# 12






**13**







16




17





**18**



19

