








GALANT



Design and Quality
IKEA of Sweden






118331

16x



123492

2x



124327

2x



101350

14x




101375

2x




122971
118137
119081
119253

16x



1x


120076
117434
118224
119030




105867

1x


1




2




3




4





5





6




7






8




9




10




11






12



13




120076
117434
118224
119030




120076
117434
118224
119030


14




15




16




17






18







↓
19





20





21




22



23





24

