








# GALANT



Design and Quality  
IKEA of Sweden






118331

10x




122971  
118137  
119081  
119253

10x



120076  
117434  
118224  
119030

1x



124327

2x




101350

8x



101375


4x




105867

1x


# 1





# 2



**3**




120076  
117434  
118224  
119030




122971    120076  
118137    117434  
119081    118224  
119253    119030


1x



120076  
117434  
118224  
119030



**4**






1x

101350



1x

101350


# 5






# 6



# 7




2x






# 8




120076  
117434  
118224  
119030



1x




9







10





11







# 12







**13**




# 14




# 15




**16**




**17**





# 18



19

