






# GALANT



Design and Quality  
IKEA of Sweden





118331

10x



122971  
118137  
119081  
119253

8x



101350

8x



101345

4x




121762

8x




139237

2x




120076  
117434  
118224  
119030

1x




158450  
158451

1x




158452  
158453

2x




130885

4x




130887

4x



146680


4x






100006

1x


1x




158597  
158599





1




# 2




# 3




4



# 5







# 6





7




8





120076  
117434  
118224  
119030


1x




120076  
117434  
118224  
119030




# 9




# 10




# 11





# 12




# 13




14







346679





346683






346682










**17**






**18**









# 19






1x



20



21

