






# LACK



Design and Quality  
IKEA of Sweden





115980

4x




108530

4x




109041

4x



120298


4x




120938

1x




# 1






# 2








**3**




4




5



6



7



# 8

