







LACK




Design and Quality
IKEA of Sweden






8x




6x




6x




8x




4x




2x




1x




4x




1




2




3




4




5




6



7



8



9

